This Page Is Inserted by IFW Operations and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):


- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

As rescanning documents will not correct images, please do not report the images to the Image Problem Mailbox.


Hajime SAIKI et al. Q80151 WIRING SUBSTRATE Filing Date: February 27, 2004 Mark Boland 202-663-7949 1 of 8

Fig. 1



Hajime SAIKI et al. Q80151 WIRING SUBSTRATE Filing Date: February 27, 2004 Mark Boland 202-663-7949 2 of 8

Fig. 2



Hajime SAIKI et al. Q80151 WIRING SUBSTRATE Filing Date: February 27, 2004 Mark Boland 202-663-7949 3 of 8

211,756,411~ Fig. 3A -501 25 Fig. 3B Fig.3c

Hajime SAIKI et al. Q80151 WIRING SUBSTRATE Filing Date: February 27, 2004 Mark Boland 202-663-7949

Fig. 4


	EXAMPLE	COMPARISON
①熱サイクル無し	0/30	8/17
2100サイクル後	0/30	26/51
→ ②500サイタル後	0/30	10/18

- 1) NO HEAT CYCLE
- ② AFTER 100 CYCLES
- 3 AFTER 500 CYCLES

٠.

Hajime SAIKI et al. Q80151 WIRING SUBSTRATE Filing Date: February 27, 2004 Mark Boland 202-663-7949 5 of 8

Fig. 5



Hajime SAIKI et al. Q80151 WIRING SUBSTRATE Filing Date: February 27, 2004 Mark Boland 202-663-7949 6 of 8

Fig. 6





Fig. 7



Hajime SAIKI et al. Q80151 WIRING SUBSTRATE Filing Date: February 27, 2004 Mark Boland 202-663-7949 7 of 8

Fig. 8





Fig. 9



Hajime SAIKI et al. Q80151 WIRING SUBSTRATE Filing Date: February 27, 2004 Mark Boland 202-663-7949 8 of 8

Fig. 10

